


PROFORMA FOR THE SAFETY OF SCHOOL BUILDING

PART- 1

(To be filled by the Head of School/ Institute)

1. Name of the School : **DOON OXFORD SCHOOL**
2. Location : **VILL. THAKARWAL, LUDHIANA**
3. Plot Area : **2.79 ACRE**
4. Plinth Area : **11284.61**
5. Number of Storey's : **GROUND FLOOR+ FIRST FLOOR**
6. Year of Construction of Building : **2014**
7. **If the building has been constructed under the supervision :**
Of the qualified Engineer, the following details may be given
 - a) Name of the Engineer with qualification : **SUKHJINDER SINGH**
 - b) Address of Engineer : **H.NO. 27, SARABHA NAGAR EXTENSION, LDH.**
 - c) Set of Structural drawings used in the construction, if available :
 - d) Name & address of Architect with qualification : **SUKHJINDER SINGH**
8. **Whether the building has been constructed for the purpose :**
 - a) School : **YES/ NO YES**
 - b) Residential Purpose and converted for use as a School : **YES/ NO -**
9. **Materials used for roofs**
 - a) R.C.C. Slabs/R.B.C. Slabs : **YES/ NO YES**
 - b) R.S. Joist & Battons : **YES/ NO**
 - c) Wooden joists & Battons : **YES/ NO**
10. **Materials used for walls**
 - a) Mud Mortar : **YES/ NO YES**
 - b) Cement Mortar : **YES/ NO**
 - c) Lime Mortar : **YES/ NO**
11. **Flooring**
 - a) Conglomerate : **YES/ NO**
 - b) Terrazo : **YES/ NO**
 - c) Brick Paving. : **YES/ NO**
12. **A detailed drawing indicating dimensions of the rooms
Alongwith size and location of doors and windows (Attached)**


Principal
DOON OXFORD SCHOOL
Thakkarwal, Pakhowal Road,
Ludhiana.

PART-II
(To be filled by the S.D.E.)

- a) I have visited the above mentioned school on dated23-11-2021.....And have Visually inspected it from all angles of safety and find it fit for normal use as School buildings.
- b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c) In case the building is affected by food, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d) This building can be safety occupied for normal use upto (indicate upto which it can be used)

.....31-3-2022.....



Sub Divisional Engineer,


Sub Divisional Engineer
Construction Sub Division No.3,
PWD B & R, Br. Ludhiana.


PWD B & R, Br. Ludhiana.

ਨੰਬਰ 256-257 ਮਿਤੀ 23/11/2021

1. ਪਿੰਸੀਪਲ Doon Oxford School Village Thakarwal, Ludhiana ਜੀ ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਜਾਣਕਾਰੀ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।
2. ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ. 1, ਲੇ.ਨਿ.ਵਿ., ਭ ਤੇ ਮ ਸਾਖਾ, ਲੁਧਿਆਣਾ ਜੀ ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਲੋੜੀਂਦੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।


Sub Divisional Engineer
Construction Sub Division No.3,
PWD B & R, Br. Ludhiana.


PWD B & R, Br. Ludhiana.